

NL: Platform tunnels and cross passages



Potential trip hazard ??



Tiles cracked/broken at the floor



Tile replaced with filling material



Tiles missing locally




Tiles exposed under cladding




Opening cladding, sealed with flexible mastic – All cross passages



Tiles cracked in the vertical wall of the opening



View of Platform tunnel (TTPA3)



Cracked floor tiles



Missing bolts on cladding



Missing bolts on cladding



Tiles exposed under cladding



Broken wall tiles above tube map



Broken tile removed under sign

During inspection it was observed that some bolts of the cladding were unscrewed/loosened or missing at places.
It is recommended that cladding is securely fixed during construction to avoid potential risk of tiles/finished falling.